



Industrial Weighing Systems

9 Richmond St. Picton, ON Canada K0K 2T0

Ph: 613-786-0016 Cell: 613-921-0397 Fax: 613-476-5293

E-mail info@iwsystems.ca Website: www.iwsystems.ca

HDCS 150



Features

Suitable for warehouse environment, shipping & receiving, small office and home use.

Heavy-Duty Stainless-Steel Platform 14"x16".

Large 1" Backlit LCD Display, easy to read from a distance & larger than most in its class.

6' Cord allows the Display to be hung on a wall (with the included hanging-brackets), or set on a table.

Display buttons, easy-to-use: Tare, Zero & Hold.

Weighing Modes:

Kilograms

Pounds

Capacity:

150.00 Kg

300.0 Lb

Resolution:

0.05 Kg

0.1 Lb

ADDITIONAL SPECIFICATIONS*

Power	AC adapter (included) 6 AA Batteries (not included)
Display	LCD
Tare Feature	YES
Calibration Feature	YES
Count Feature	NO
Platform Size	16" x 14" x 2.25"
Display Size	10.75" x 3.75"
Weighing Modes	2, (Lb/Kg)

Auto Off Instructions

Step 1: Turn the scale off

Step 2: Turn the scale on while pressing the [Z/T] button – the scale will show "SET"

Step 3: Continue to hold the [Z/T] button – Press the [P] key 3 times until "A-OFF" is displayed

Step 4: Release the [Z/T] button. Press the [U] button to enter the menu.

Step 5: The Auto-off can now be adjusted by pressing the [P] button.